



BRENTWOOD REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012677	Cooler	1	In hallway adjacent to computer lab Left High	WT-042916-12694- A	< 1	WT-042916-12694- B	< 1				
2	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012678	Cooler	1	In hallway adjacent to computer lab Right Low	WT-042916-12695- A	< 1	WT-042916-12695- B	< 1				
3	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012679	Classroom	1	In arts and crafts room 102	WT-042916-12696- A	< 1	WT-042916-12696- B	< 1				
4	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012680	Classroom	1	In kitchen room 105	WT-042916-12697- A	< 1	WT-042916-12697- B	< 1				
5	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012683	Fountain	1	Exterior of building adjacent to basketball court Left High	WT-042916-12700- A	1.4	WT-042916-12700- B	1				
6	BRENTWOOD RECREATION CENTER	5/24/2016	WS- 012684	Fountain	1	Exterior fountain adjacent to basketball court Right Low	WT-042916-12701- A	< 1	WT-042916-12701- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.